4-Point Inspection Form

Insured/Applicant Name: Jenine Loving Application / Policy #:

Address Inspected: 9517 River Otter Dr, Fort Myers, FL 33912

Actual Year Built: 2015 Date Inspected: 12/4/2024

Minimum Photo Requirements:

- ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- ☑ Main electrical service panel with interior door label
- ☑ Electrical box with panel off
- ☐ **All** hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: ☑ Circuit breaker ☐ Fuse

Total Amps: 200

Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)

Second Panel

Type: ☐ Circuit breaker ☐ Fuse

Total Amps:

Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)

Indicate presence of any of the following:

- ☐ Cloth wiring
- ☐ Active knob and tube
- ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):

* If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*

- ☐ Connections repaired via COPALUM crimp
- ☐ Connections repaired via AlumiConn

Hazards Present

- ☐ Blowing fuses
- ☐ Tripping breakers
- ☐ Empty sockets
- ☐ Loose wiring
- ☐ Improper grounding
- ☐ Corrosion
- ☐ Over fusing
- ☐ Double taps
- ☐ Exposed wiring
- ☐ Unsafe wiring
- ☐ Improper breaker size
- ☐ Scorching
- ☐ Other (explain)

General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory **(explain)**

Supplemental information

Main Panel

Panel age: 9

Year last updated: 2015

Brand/Model: Eaton

Second Panel

Panel age:

Year last updated:

Brand/Model:

Wiring Type

☑ Copper

☑ NM, BX or Conduit

4-Point Inspection Form

HVAC System

Central AC: ☑ Yes ☐ No

Central heat: ☑ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: _____

Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)

Date of last HVAC servicing/inspection: N/A

Hazards Present

Wood-burning stove or central gas fireplace *not* professionally installed? ☐ Yes ☑ No

Space heater used as primary heat source? ☐ Yes ☑ No

Is the source portable? ☐ Yes ☑ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?
☐ Yes ☑ No

Supplemental Information

Age of system: 9 and 1

Year last updated: 2015 and 2023

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☑ No

Is there any indication of a prior leak? ☐ Yes ☑ No

Water heater location: Garage- 2022

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A
Dishwasher	☑	☐	☐
Refrigerator	☑	☐	☐
Washing machine	☑	☐	☐
Water heater	☑	☐	☐
Showers/Tubs	☑	☐	☐

	Satisfactory	Unsatisfactory	N/A
Toilets	☑	☐	☐
Sinks	☑	☐	☐
Sump pump	☐	☐	☑
Main shut off valve	☑	☐	☐
All other visible	☑	☐	☐

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping System:

2015 Original to home

_____ Completely re-piped

_____ Partially re-piped

(Provide year and extent of renovation in the comments below)

Type of pipes (check all that apply)

☐ Copper

☑ PVC/CPVC

☐ Galvanized

☑ PEX

☐ Polybutylene

☐ Other (specify)

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Concrete tile

Roof age (years): 9

Remaining useful life (years): 16

Date of last roofing permit: Original from year built

Date of last update:

If updated (check one):

- ☐ Full replacement
- ☐ Partial replacement

% of replacement:

Overall condition:

- ☑ Satisfactory
- ☐ Unsatisfactory **(explain below)**

Any visible signs of damage / deterioration?
(check all that apply and explain below)

- ☐ Cracking
- ☐ Cupping/curling
- ☐ Excessive granule loss
- ☐ Exposed asphalt
- ☐ Exposed felt
- ☐ Missing/loose/cracked tabs or tiles
- ☐ Soft spots in decking
- ☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☑ No
Attic/underside of decking ☐ Yes ☑ No
Interior ceilings ☐ Yes ☑ No

Secondary Roof

Covering material:

Roof age (years):

Remaining useful life (years):

Date of last roofing permit:

Date of last update:

If updated (check one):

- ☐ Full replacement
- ☐ Partial replacement

% of replacement:

Overall condition:

- ☐ Satisfactory
- ☐ Unsatisfactory **(explain below)**

Any visible signs of damage / deterioration?
(check all that apply and explain below)

- ☐ Cracking
- ☐ Cupping/curling
- ☐ Excessive granule loss
- ☐ Exposed asphalt
- ☐ Exposed felt
- ☐ Missing/loose/cracked tabs or tiles
- ☐ Soft spots in decking
- ☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☐ No
Attic/underside of decking ☐ Yes ☐ No
Interior ceilings ☐ Yes ☐ No

Additional Comments/Observations (use additional pages if needed):

Plumbing systems- Plumbing is original from year built. Water heater was replaced in 2022.
Electrical systems- Main service panel is original from year built.
HVAC- Air handler 1 and condenser 1 are original from year built. Air handler 2 and condenser 2 were replaced in 2023.
Roof- Concrete tile roof covering is original from year built.

All *4-Point Inspection Forms* must be completed and signed by a verifiable Florida-licensed inspector.
I certify that the above statements are true and correct.

Inspector Signature	Title	License Number	Date
Matthew Foster	Home Inspector	HI13455	December 05, 2024

Company Name	License Type	Work Phone
MEF Home Inspections LLC	Home Inspector	941-740-9635

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Additional Pictures

Address



Front



Right side



Rear



Roof



Roof



Additional Pictures

Roof



Roof



Condensers



Condenser manufacture label



Condenser manufacture label



Air handler



Additional Pictures

Air handler manufacture label




Air handler



Main service panel cover on



Main service panel cover off



Water heater



TPR



Additional Pictures

Water heater manufacture label



Plumbing at kitchen sink



Supply lines at kitchen sink



Plumbing at 2nd shared bathroom sink



Supply line at 2nd shared bathroom toilet



Plumbing at kitchen sink



Additional Pictures

Supply lines at kitchen sink



Plumbing at 1st shared bathroom sink



Supply line at 1st shared bathroom toilet



Plumbing at master bathroom sink



Plumbing at master bathroom sink



Supply line at master bathroom toilet

